



FAB-JET II Adhesive Backed Fabric

FAB-JET II is an ultra removable adhesive backed polyester fabric. It features an opaque print surface that is water resistant and OBA free. The ink jet receptive coating is compatible with solvent, eco-solvent, UV curable and Latex printers. FAB-JET II delivers high color gamut, fine line definition and photo realistic image quality. It cuts easily around fine detail without fray or release liner separation. The micro-sphere adhesive is ultra removable and leaves little or no adhesive residue. When installed to clean surfaces FAB-JET II can be applied and removed multiple times. It is suitable for outdoor promotional applications on windows, doors, bus shelters, sign boards and other flat surfaces.

Applications:

Ideal for finished surfaces that are flat, smooth and clean. Premium interior applications for sealed walls, displays, glass, film, cabinets, metal and plastic. Promotional outdoor applications including vehicle's, bus shelters, sandwich boards, doors and windows. Note: Minimum application temperature above 40° F.

Advantages:

- Will adhere to and remove cleanly from any flat non-porous surface.
- Excellent opacity
- Exceptional tear strength
- Photographic print quality

Printer Settings:

Settings will vary by printer model and ink platform. Heater setting of 95° F on pre-heat, platen heat and post-heat are a good starting point. Excessive heat can change the adhesive properties. Choose matte calendared vinyl or fine art paper profile.

Printing Platforms:

- Eco-Solvent, Solvent and UVcurable and Latex printers.

Specifications:

Base material: Polyester

Adhesive: Removable acrylic, PSTC-101 180° peel
4 to 12oz./in.

Thickness: 8 mil including adhesive.

White Point: 96* L Value

Shelf Life: 6 months (storage conditions 70° F & 50% humidity.)

Finishing:

Lamination is not recommended. Clear spray coatings may be used (test first).

Information provided here is based on research and is believed to be reliable as of printing date. This information does not constitute a warranty. All material should be tested by purchaser to determine final suitability. Quality will not be held responsible for customers end use of product. Quality is available for directions and advice as to proper use and application of our products.

Catalog #	Size
7130	30" x 100'
7142	42" x 100'
7154	54" x 100'
7160	60" x 100'

To order call:
(800)552-9427
www.qmls.com
info@qmls.com
fax (203)281-6451



FAB-JET II Adhesive Backed Fabric

Guideline for Success

5 factors that will effect longevity and performance.

1. Receiving surface:

Always pre-test surfaces for suitability. A textured surface provides less contact area than a smooth surface. A soft roller under pressure will assist adhering to wall contours. Dust and dirt will act as a barrier. Clean the receiving surface thoroughly and allow plenty of time to dry. Do not use chemical cleaners.

2. Ink:

Over-inking will adversely affect the adhesive on any material including this product.

Solvent Ink that has not outgassed completely before applying will shorten lifespan of adhesion.

UVcure ink with lamps set too hot could change the adhesive properties.

3. Environment:

Graphics applied in conditions below 40 degrees will shorten life span.

Dirt, dust, oils or solvents introduced from environment could affect bond.

Natural elements such as UV light, moisture and extreme cold can interfere with application.

4. The Graphic:

FabJet II can be printed and machine cut to the edge of the graphic. Very thin cuts and corners that come to a point have the greatest chance to release from a surface. Use rounded corners and a safe edge whenever possible. Allow at least 24 hours of cure time before cutting and installation.

5. Removal:

Break the bond at the top of the graphic and slowly pull away from the wall at 180 degree angle. This will minimise the likelihood of any adhesive residue or surface damage.

Information provided here is based on research and is believed to be reliable as of printing date. This information does not constitute a warranty. All material should be tested by purchaser to determine final suitability. Quality and its suppliers will not be held responsible for customers end use of product. Quality is available for directions and advice as to proper use and application of our products.

To order call:
(800)552-9427
www.qmls.com
info@qmls.com
fax (203)281-6451